

EXPLANATION


- Gulfco Marine Maintenance Site Boundary (approximate)
- BERA Sediment Sample Location

Notes:
The background soil sample area is shown on Figure 1 (and Figure 14 of the Nature and Extent Data Report - May 20, 2009).

- J - Estimated Value
- H - Bias in results likely to be high
- DW - Dry Weight

- = High Concentration
- = Mid Concentration
- = Low Concentration

All Concentrations in mg/kg DW



Approx. Scale in Feet

0 60 120

Source of photo: H-GAC, Texas aerial photograph, 2006.

TITLE:

**NORTH AREA SOIL
SAMPLE LOCATIONS**

REPORT:

FINAL BASELINE ECOLOGICAL RISK ASSESSMENT

SITE:

GULFCO MARINE MAINTENANCE
FREEPORT, BRAZORIA COUNTY, TEXAS

PROJECT:

41568745

DRAWN:

ZGK/NAB

CHECKED:

DL

FIGURE:

3

DATE:

MARCH, 2011

10550 RICHMOND AVE., SUITE 155
HOUSTON, TEXAS 77042
PH: 713-914-6699
FAX: 713-914-8404